

Dangerous Waste Annual Report Verification Form - 1996

Washington State Department of Ecology **Hazardous Waste Information** WASHINGTON STATE P.O. Box 47658

E C O L O G Y Olympia, WA 98504-7658 (800) 874-2022 (within state) (360) 407-6170

For Ecology Use Only Date Received: MAY 2 0 1997			
Form	Review	Data Entry	Verification
VF		`.	(i)
GM			
WR			
OI			

RCRA Site	Name: Alaskan Copper Works		Did the ownership of this company change in 1996?
Site Locati	OLOG GITTAVE G		YES Date:
		County: KING	If yes, provide new owner
	evenue Tax Registration Number: (b) (6)	SIC: 5051	information in 2b. below.
	company name if different from above:		Legisland W. M. E. Leaving
	formation shown in the left column, and make cumn. If the box on the left is blank, please fill in		JUN 2 3 1997
a Then	nailling address for this site is:	tb.	See the second s
Name:	Alaskan Copper Works	Name:	Assert Constitution of the
Address:	P.O. Box 3546 SEATTLE, WA 98124	Address:	THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON AND ADDRESS OF
2a The c	ompany/agency owner of this site is:	2b	
Name:	Alaskan Copper & Brass Companies Inc	Name:	
Address:	P.O. Box 3546 Seattle, WA 98124	Address:	
Phone:	(206) 623-5800	Phone:	
Ba Thep	roperty owner of this site is:	3b	
Name:	Rosen Investment Company	Name:	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
Address:	P.O. Box 3546	Address:	3
Phone:	Seattle, WA 98124 (206) 623-5800	Phone:	
TOTOTON THE TOTO MANAGE MANAGEMENT OF	ontact for site visits and inspections is:	4b	
		1	
Name:	James Brown	Name:	se "mg d d'anne" " d
Address:	3200 6th Ave S Seattle, WA 98134	Address:	
Phone:	(206) 623-5800	Phone:	
ia. The co	ontact for annual report forms is:	.5b	
		Name:	
Name:	Rodney L. Pearcey	i realite.	
Name: Address:	Rodney L. Pearcey 3200 6th Ave S Seattle, WA 98134	Address:	

Ecy 020 - 109

dicate the facility's generator status for 1996 by che	cking the appropriate boxes:
Generator Status Large Quantity Generator (LQG) Medium Quantity Generator (MQG) Small Quantity Generator (SQG) No regulated dangerous waste generated	Transportation Activity Transporter for your own waste Transporter for commercial purposes Treatment, Storage, Disposal, Recycling (TSDR) Facility For waste generated at this facility For waste generated by other facilities
. Report Summary	
ease check off which additional forms are included	in this report, if any, and provide the total number of pages.
M Generation and Management (GM) Form	,
Off-site Identification Information (OI) Form	
Waste Received (WR) Form	
Total Number of pages submitted	
equired under EPA's Biennial Report. Ecology is those in that report. I certify under penalty of law that this document and accordance with a system designed to assure that question the person or personathering the information, the information submitted arm aware that there are significant penalties for substitution in the information of the person or personathering the information, the information submitted arm aware that there are significant penalties for substitutions.	resentative of the company/agency. This certification language is is required to implement reporting requirements at least as stringers all attachments were prepared under my direction or supervision in qualified personnel properly gather and evaluate the information resons who manage the system, or those persons directly responsible for is, to the best of my knowledge and belief, true, accurate and complete. mitting false information, including the possiblity of fine and imprisonment.
Signature (in ink) Name (print/type) David Glever	
The Country of the Co	
Date 3/28/97	

10

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams.

Then complete one answer sheet for each waste stream.

PLEASE ENTER: YOUR RCRA SITE ID #: WAD 980 738546 Site name: ALASIKAN COPPER WORKS
FOR ECOLOGY USE ONLY: Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of Dan	gerous Waste Stream		
A-1. 975 (options	al)		
A-2. PARTS WASH	ER SOLVENT 150 (PETROLEUM NAPHTH	JA)_
A-3. Doog 1018 1039	DO40	A-4	
A-5. ☐ EHW ☑ DW	A-6. ∑ No □ Yes	A-7. A 19	
A-8. B Z(1 A-9.)	(i	, answer A-9.a.)	
. ibiri 🔻 - Mi	A-9.a. N	Λ	
B. Waste Managemen	t Activities		
B-1. 80 🗆 ST	OMTOP OK AG	L C (If G, L, or C, answe	er B-1.a.)
	B-1.a. 6.7	Lbs/gal ☐ Specific Gravity☐	Lbs/yd³
B-2. On-site Off-si	te 🛚 Both		
B-3. M	B-3a. □ Yes No □ D	OK B-3b. □ Yes 🕅 No □ DI	K
B-4. i. Designated Facility (ID Numbers ORD 98 1 7661)		ii. Quantity iv. Recycling 91%	Percent
g Program State St		Page	

PLEASE ENTER:	
YOUR RCRA SITE ID #:	
Site name:	

B-5. If additiona	al space is required	l, use continuation	n sheet on the following	page.
i. Date Shipped (mm/dd)	ii . Manifest Document Number	iii. Internal Tracking Code (optional)	iv. Desigation Facility (TSDR) RCRA Site ID Number	v. Quantity Shipped

ALIENTA TO A STATE OF THE STATE				
				C
		2		
-				THE RESERVE THE PROPERTY OF THE PERSON OF TH
	1			
Carrier Communication of the C	democratic per programme and a second control of the second contro	with the state of		**************************************
		8		

		-		
(
C. Comments	5			
		0 1		

Page ____

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #: WAD 986739546
Site name: ALASKAN COPPER WORKS
FOR ECOLOGY USE ONLY:
Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of	f Dangerou	s Waste Stream		
A-1((optional)		an english	Sur
A-2. THINNER				
A-3. DOOL			A-4	
A-5 . □ EHW 🔀	DW A	1-6. ⊠ No □ Yes	A-7. A 19	
A-8 . B <u>7.05</u>	A-9 (⊠(i □	ii 🗖 iii 🗎 iv 🔲 v (If	v, answer A-9.a.)	× A
	No Papagagas	A-9.a.	M	
B. Waste Manage	ement Acti	vities		
B-1. 357. 78	□ST □MT	ØP □K □G	□L □C(If G, L	., or C, answer B-1.a.)
		B-1.a	Lbs/gal 🗖 Specif	ic Gravity ☐ Lbs/yd³
B-2. ☐ On-site	roff-site □ B	oth	Mark Artista and St	
B-3.	M	B-3a. ☐ Yes No ☐	DK B-3b. 🗆 Ye	esÆNo □ DK
B-4. i. Designated Fa ID Numbers WAD991221	acility (TSDR)	ii . System Code M M M M	357.78	
				Page

BOOK 1: 1996 FORMS AND INSTRUCTIONS

PLEASE ENTER:
YOUR RCRA SITE ID #:
Site name:

B-5. If additiona	al space is required	, use continuation	sheet on the following	page.
i. Date Shipped (mm/dd)	ii . Manifest Document Number	iii. Internal Tracking Code (optional)	iv. Desigation Facility (TSDR) RCRA Site ID Number	v. Quantity Shipped
•				
	THE STATE OF THE S			
			-	
		1		
			4	
***************************************		1		
****			-1	
				,
C. Comments	S			
			Marie Company	

BOOK 1: 1996 FORMS AND INSTRUCTIONS

Page _

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams.

Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #:WAD 980739546
Site name: ALASKAN COPPER WORKS
FOR ECOLOGY USE ONLY:
Date received:
V 1

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of Dangerou	s Waste Stream	
A-1 (optional)		
A-2. DOMINO INK & MEK	BASED LEANER	
A-3. DODI FOOS		A-4
A-5. DEHW ADW	1-6. Ø (No □ Yes	A-7. A
A-8. B 209 A-9. (1)	ii □iii □iv □v(lfv,	answer A-9.a:)
	A-9. a. M	
B. Waste Management Acti	vities	
B-1. 140.11 DST DMT	PP DK DG D	L C (If G, L, or C, answer B-1.a.)
	B-1.a 🗆 L	bs/gal ☐ Specific Gravity☐ Lbs/yd³
B-2. ☐ On-site ☐ Off-site ☐ B	oth	
B-3 M	B-3a. ☐ Yes Ø No ☐ Di	K B-3b. ☐ Yes No ☐ DK
B-4. i. Designated Facility (TSDR) ID Numbers WA04(1281767		Quantity iv. Recycling Percent

BOOK 1: 1996 FORMS AND INSTRUCTIONS

PLEASE ENTER:
YOUR RCRA SITE ID #:
Site name:

B-5. If additional space is required, use continuation sheet on the following page.					
i. Date Shipped (mm/dd)	ii . Manifest Document Number	iii. Internal Tracking Code (optional)	iv. Desigation Facility (TSDR) RCRA Site ID Number	v. Quantity Shipped	
				/	
6-4-19-19-19-19-19-19-19-19-19-19-19-19-19-					
	-27				
				S	
-	- 6-18-19-19-19-19-19-19-19-19-19-19-19-19-19-				
	•	•			

			*		
C. Comment	S				

BOOK 1: 1996 FORMS AND INSTRUCTIONS

Page .

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

PLEASE ENTER:				
YOUR RCRA SITE ID #: WAD 980738546				
Site name: ALASKAN COPPER WORKS				
FOR ECOLOGY USE ONLY:	1, 2 = 2			
Date received:				

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of Dangerous Waste Stream					
A-1.	(optional)				
A-2. LOOSTE PA	CK OF FLA	MMABLE PAINTS			
A-3.0001 DOOR	12635			A-4	
A-5. □ EHW ⅓	Q DW	A-6. / ∆ (No □ Ye	es	A-7. A 59	3
A-8 . B <u>203</u>	A-9. Æi □	lii Oiii Oiv Ov	(If v, a	nswer A-9.a.)
		A-9.	a. M _		- 1 m
B. Waste Mana	gement Act	ivities			
B-1. 1600	□ST □M	r Ø€ □K □G	۵L	□ C (If G	a, L, or C, answer B-1.a.)
		B-1.a	Lbs	s/gal 🗆 Spe	cific Gravity□ Lbs/yd³
B-2. □ On-sitę	Ø Off-site □ E	Both			
B-3	M	B-3a. ☐ Yes 🎾 No	□ DK	В-3ь. 🗆	Yes No □ DK
B-4. i. Designated ID Numbers	Facility (TSDR)	ii . System Code M <u>65 1</u> M M	_(× ×	iv. Recycling Percent

BOOK 1: 1996 FORMS AND INSTRUCTIONS

27

Page

PLEASE ENTER:
YOUR RCRA SITE ID #:
Site name:

B-5. If additiona	al space is required	, use continuation	sheet on the following	page.
i. Date Shipped (mm/dd)	ii . Manifest Document Number	iii. Internal Tracking Code (optional)	iv. Desigation Facility (TSDR) RCRA Site ID Number	v. Quantity Shipped
			ATT	
		A STATE OF THE STA		
•				
400				1

	1			

C. Comments	s	Đ		
		-		
2				

BOOK 1: 1996 FORMS AND INSTRUCTIONS

28

Page .

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams.

Then complete one answer sheet for each waste stream.

PLEASE ENTER: YOUR RCRA SITE ID #: WAD980738546 Site name: ALASKAN COPPER WORKS
FOR ECOLOGY USE ONLY: Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description	of Dangero	ous Waste Stream	
A-1.	(optional)		
A-2. LAB PACK	CORROSI	VE ALID	
A-3. DOOZ			A-4
A-5. 🔾 EHW 🔏	S DM	A-6. Ø No □ Yes	A-7. A 99
A-8. B <u>007</u>	A-9. 1	□ ii □ iii □ iv □ v (If v,	answer A-9.a.)
		A-9.a. M	
B. Waste Manag	gement Ac	tivities	
B-1. <u>80</u>	□ST □N	AT PAP OK OG O	L C (If G, L, or C, answer B-1.a.)
		B-1.a 🖵 L	bs/gal ☐ Specific Gravity☐ Lbs/yd³
B-2. ☐ On-site	Off-site	Both	
B-3	M	B-3a. ☐ Yes 🎾 No ☐ DI	K B-3b. □ Yes No □ DK
B-4. i. Designated ID Numbers	Facility (TSDR S 多1子6子	ii. System Code iii M_132 M M M	
			Page

BOOK 1: 1996 FORMS AND INSTRUCTIONS

PLEASE ENTER:
YOUR RCRA SITE ID #:
Site name:

i. Date Shipped (mm/dd) ii. Manifest Document iii. Internal Tracking (code (optional) ii. Dasigation Facility (TSDR) v. Quantity Shipped RCRA Site ID Number v. Quanti	B-5. If addition	al space is required	l, use continuation	n sheet on the following	page.
	i. Date Shipped (mm/dd)	ii . Manifest Document Number	iii. Internal Tracking Code (optional)	iv. Desigation Facility (TSDR) RCRA Site ID Number	v. Quantity Shipped
				5 (2)	
				-	
			······································		
C. Comments					
C. Comments					
C. Comments					
C. Comments					
C. Comments					
C. Comments			e:		
C. Comments					
C. Comments					
C. Comments					
	C. Comment	S	e e e e e e e e e e e e e e e e e e e	ATTICLE TO THE PARTY OF THE PAR	

BOOK 1: 1996 FORMS AND INSTRUCTIONS

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams.

Then complete one answer sheet for each waste stream.

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

					-,
A. Description	of Dangero	us Waste St	ream		
A-1	(optional)				
A-2. LAB PACK	CORRO	SIVE ALKA	LINE		
A-3.0062				A-4	
A-5. ☐ EHW /	S DW	A-6. X No	☐ Yes	A-7 . A <u>99</u>	- 3
A-8. B 009	A-9. ♥i □	oji ojii ojv	□ v (If v,	answer A-9.a.)	
	m² +3 g = 4		A-9.a. M		
B. Waste Manag	gement Act	ivities			
B-1. 80	□ST □M	T Ø P □ K	□ G □	L C (If G, L, or	C, answer B-1.a.)
		B-1.a.	DLI	bs/gal ☐ Specific G	ravity□ Lbs/yd³
B-2. On-site	Ø Off-site □ I	3oth			
B-3	M	B-3a. □ Yes	ÉLNO DA	B-3b. ☐ Yes 2	No □ DK
B-4. i. Designated ID Numbers	Facility (TSDR)	ii. System M 132 M M M		. Quantity iv. I	Recycling Percent

PLEASE ENTER:
YOUR RCRA SITE ID #:
Site name:

B-5. If addition	al space is required	l, use continuation	n sheet on the following	page.
i. Date Shipped (mm/dd)	ii . Manifest Document Number	iii. Internal Tracking Code (optional)	iv. Desigation Facility (TSDR) RCRA Site ID Number	v. Quantity Shipped
	500 Co. 1800			
		1		
				
	<u> </u>			
C. Comments	S			
<u></u>	·.			

BOOK 1: 1996 FORMS AND INSTRUCTIONS

Page _

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams.

Then complete one answer sheet for each waste stream.

PLEASE ENTER: YOUR RCRA SITE ID #: WAD 986738546 Site name: ALASKAN COPPER WIRKS
FOR ECOLOGY USE ONLY: Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of Da	ingerous Waste Stream	
A-1. (option	onal)	
A-2. LAB PACK -	TOXIC	
A-3. U080		A-4
A-5. 🗆 EHW 📈 DW	A-6. ÆNo ☐ Yes	A-7 . A <u>99</u>
A-8. B 009 A-9	.☆i □ii □iii □iv □v(Ifv,	answer A-9.a.)
	A-9.a. M	
B. Waste Manageme	ent Activities	
B-1 . <u>90</u> □ s	т 🗆 МТ 💢 Р 🗆 К 🗀 С 🗆	L C (If G, L, or C, answer B-1.a.)
	B-1.a. 🔲 L	.bs/gal □ Specific Gravity□ Lbs/yd³
B-2. ☐ On-site ☐ Off-	site 🗅 Both	
B-3	M B-3a. ☐ Yes 🗖 No ☐ D	K B-3b. ☐ Yes No ☐ DK
B-4. i. Designated Facility ID Numbers WAD 991 281 7-6	(TSDR) ii . System Code iii . 3	i. Quantity iv. Recycling Percent

BOOK 1: 1996 FORMS AND INSTRUCTIONS

PLEASE ENTER:	
YOUR RCRA SITE ID #:	
Site name:	

			sheet on the following	
i. Date Shipped (mm/dd)	ii . Manifest Document Number	iii. Internal Tracking Code (optional)	iv. Desigation Facility (TSDR) RCRA Site ID Number	v. Quantity Shipped
)				

-				
			· ·	
			-	;
3				

1				
			-	
-			2	
C. Comment	S			

				-

BOOK 1: 1996 FORMS AND INSTRUCTIONS

Page_

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description	A. Description of Dangerous Waste Stream				
A-1	-1 (optional)				
A-2. SODIUM	CYANIDE	SOLID			
A-3. DOO3 Plob				A-4	
A-5.	DW DW	A-6. No	☐ Yes	A-7. A 59	3
A-8. B 3/2	A-9. Ø	aji ajii ajv	□ v (If v,	answer A-9.a.))
		41	A-9.a. M		
B. Waste Mana	gement Ac	tivities			
B-1	UST UM	IT Ø P □ K	□ G □	L 🗆 C (If G	, L, or C, answer B-1.a.)
,		B-1.a.	0	bs/gal 🖸 Spe	cific Gravity□ Lbs/yd³
B-2. On-site	Off-site 🗆	Both			
B-3	M	_ B-3a . □ Yes Ø	(No □ DK	B-3b. 🗆	Yes Ø No ☐ DK
B-4. i. Designated ID Number WAD 9917.	Facility (TSDR s さけんオ	ii. System C M <u>043</u> M M M	N	Quantity 1 R	iv. Recycling Percent

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams.

Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #: LAD 980738546
Site name:
FOR ECOLOGY USE ONLY:
Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of Dangerous Waste Stream						
A-1.	A-1 (optional)					
A-2. DISCARDE	D CONAF	ADABNE PART B				
A-3		-	A-4. WTO2			
A-5 . □ EHW 🎉	DW	A-6. 🗷 No 🗆 Yes	A-7. A 58			
A-8. B 606	A-8. B 600					
i ya.	A-9.a. M					
B. Waste Mana	gement A	Activities	eg Trade Tra			
B-1. 200	□ ST □	IMT DYP OK OG O	L D C (If G, L, or C, answer B-1.a.)			
	B-1.a ☐ Lbs/gal ☐ Specific Gravity ☐ Lbs/yd					
B-2. On-site Off-site Debth						
B-3	M	B-3a. ☐ Yes A No ☐ DI	K B-3b. ☐ Yes (No ☐ DK			
B-4. i. Designated ID Number WAD 91178	Facility (TSI s 1767	DR) ii . System Code iii M				
		e film * Page 18	Page			

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copics of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #: WAP980738546
Site name: ALASKAN COPPER WORKS
FOR ECOLOGY USE ONLY:
Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

	, , , , , , , , , , , , , , , , , , , ,					
A. Description	of Dange	erous Waste Stream	•			
A-1	(optional)	* -				
A-2. DISCARDE	D SOLID	SODIUM HYDROXIDE				
A-3			A-4. WSCZ WTOZ			
A-5 . □ EHW	₹ DW	A-6. Ø(No ☐ Yes	A-7. A <u>58</u>			
A-8. B <u>306</u>	A-9, () i	□ ii □ iii □ iv □ v (If v,	answer A-9.a.)			
		A-9.a. M	l			
B. Waste Management Activities						
B-1. 250	B-1. 250 OST OMT POK OG OL OC (If G, L, or C, answer B-1.a.)					
		B-1.a 🗆 L	bs/gal □ Specific Gravity□ Lbs/yd³			
B-2. On-site	Off-site	☐ Both				
B-3.	M	B-3a. ☐ Yes A No ☐ D	K B-3b. ☐ Yes A No ☐ DK			
B-4. i. Designated ID Numbers	Facility (TSI		i. Quantity iv. Recycling Percent			
y Avenue Alexandra			Page			

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #: WAD980738546
Site name: ALASKAN COPPER WORKS
FOR ECOLOGY USE ONLY:
Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description	of Danger	ous Waste Stream			
A-1	_ (optional)	30.79			
A-2.CRYSTALLIN	IE CORROS	IVE SOLID WITH CHR	OMIUM TANNEAL SLAG		
A-3. Dxx27			A-4		
A-5. □ EHW	DW	A-6. ∕ No ☐ Yes	A-7. A		
A-8. B 316	A-9. 21		answer A-9.a.)		
		A-9.a. N			
B. Waste Management Activities					
B-1. 250-7 DST DMT P DK DG DL DC(If G, L, or C, answer B-1.a.)					
B-1.a ☐ Lbs/gal ☐ Specific Gravity☐ Lbs/yd³					
B-2. 🗆 On-site	Off-site 🗆	Both			
B-3	M	B-3a. ☐ Yes A No ☐ D	K B-3b. ☐ Yes ØNo ☐ DK		
B-4. i. Designated ID Number	Facility (TSDI s 1767	R) ii. System Code ii M	i. Quantity iv. Recycling Percent		

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #: WAD 980738546 Site name: ALASKAN COPPER WORKS
FOR ECOLOGY USE ONLY:
Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description	of Dangero	us Waste Stream		
A-1	(optional)			
A-2. PAINT WA	KIE			
A-3. 2601 0007	FOOZ FOO	3	A-4	×
A-5. □ EHW	Z DW	A-6. No ☐ Yes	A-7. A <u>09</u>	
A-8. B <u>204</u>	A-9.	ii 🗆 iii 🗀 iv 🖸 v (If v	, answer A-9.a.)	
	· ·	A-9.a. N	1	
B. Waste Management Activities				
B-1.513.74	ОЅТ ОМ	тде шк ша с	IL □C (If G, L, or C, an	swer B-1.a.)
		B-1.a 🔾	_bs/gal ☐ Specific Gravity	√□ Lbs/yd³
B-2. On-site	Ø Off-site □ I	Both		to e
В-3.	M	. B-3a. □ Yes 🗖 No 🗆 D	K B-3b. □ Yes No □) DK
B-4. i. Designated ID Number WAD 1128	Facility (TSDR)	ii. System Code ii. M △ 5 (ii. Quantity iv. Recyc	ling Percent

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #: WO80738546
Site name: ALASKAN COPPER WORKS
FOR ECOLOGY USE ONLY:
Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of Dangero	us Waste Stream					
A-1 (optional)						
A-2. 395 DEGREASER						
A-3. Dool Fool		A-4				
A-5. DEHW ADW	A-6. (XÓ) No □ Yes	A-7. A 19				
A-8. B 207 A-9. Xi	ii □iii □iv □v(lfv,	answer A-9.a.)				
	A-9.a. M	<u>:</u>				
B. Waste Management Activities						
B-1. 141.78 DST DMT	TAP DK DG D	L C (If G, L, or C, answer B-1.a.)				
	B-1.a. ☐ Lbs/gal ☐ Specific Gravity☐ Lbs/yd³					
B-2. On-site Off-site D	Both					
B-3 M	B-3a. ☐ Yes A No ☐ Di	〈 B-3b. ☐ Yes Ø No ☐ DK				
B-4. i. Designated Facility (TSDR) ID Numbers WAD911181767	ii . System Code iii M M M	. Quantity iv. Recycling Percent				
		Page				

Please enter your RCRA Site ID number and site name at right, before making as many two-sided copies of this answer sheet as you will need to report each of your waste streams. Then complete one answer sheet for each waste stream.

PLEASE ENTER:
YOUR RCRA SITE ID #: WAD980738546
Site name: ALKKAN COPPER WORKS
FOR ECOLOGY USE ONLY:
Date received:

Be sure to reference the instructions as you complete this form. Please type or print legibly in blue or black ink.

A. Description of Dangero	ous Waste Stream				
A-1 (optional)					
A-2. X-RAY COOLAN	T				
A-3. Dool		A-4			
A-5. DEHW DW	A-6. Ø No ☐ Yes	A-7. A <u>99</u>			
A-8. B Zol A-9. 1 1	□ii □ii □iv □v(Ifv,	answer A-9.a.)			
* ************************************	A -9.a. M	· ·			
B. Waste Management Activities					
B-1. 75.06 DST DM	пДе □к □с □	L C (If G, L, or C, answer B-1.a.)			
	B-1.a 🗆 L	bs/gal □ Specific Gravity□ Lbs/yd³			
B-2. ☐ On-site ☑ Off-site ☐ Both					
B-3 M	B-3a. 🗆 Yes 🔼 No 🗀 Dr	K B-3b. ☐ Yes (No ☐ DK			
B-4. i. Designated Facility (TSDR) ID Numbers WAD 41231767) ii . System Code iii	Quantity iv Recycling Percent			

10 966

OFF-SITE IDENTIFICATION INFORMATION FORM ANSWER SHEET

Please enter your RCRA Site ID number and site name at right, before making as many copies of this two-sided answer sheet as you will need.

PLEASE ENTER: Your RCRA Site ID #: WAD 98 Site name: ALASKAN COPE				
FOR ECOLOGY USE ONLY: Date received:	i,			

Please complete this form if your facility received dangerous waste from off-site or shipped dangerous waste off-site during 1996.

P	lease type or print legibly in blue or black ink.
RCRA Site ID Number: CAD980584510	
Name: ALL WASTE TRANSPORTATION &	REMEDIATION
Address: 1801 W. WATKINS	
PHEONIX AZ 8	
Handler type: (Check all that apply.) 🗖 Generator	Transporter TSDR
RCRA Site ID Number: CAD 0592407 13	
Name: MCNOTTINGHAM CO. OF SO. CAL	-,
Figure 1	the same that th
Address: 1415 E. 9th	
POMONA CA 91766	<u> </u>
Handler type: (Check all that apply.) Generator	Transporter TSDR
RCRA Site ID Number: WAB 00001743	
Name: BURLINGTON ENVIRONMENTAL	
Address: 20245 77 AVENUE SO.	And the second s
KENT, WA 98032	
Handler type: (Check all that apply.) ☐ Generator	Transporter TSDR
Comments:	
	1900 100 100 100 100 100 100 100 100 100
7.4.	British and the Carlotter Share and the prince

BOOK 1: 1996 FORMS AND INSTRUCTIONS

33

Page

PL	EA	SE	EN	TER:
----	----	----	----	------

YOUR RCRA Site ID #: WAD980736546
Site name: ALASKAN COPPER WORKS

RCRA Site ID Number: WAD 991 Z81 767 Name: BURLINGTON ENVIRONMENTAL, INC.
Name. Box Meter Pry North Miles
Address: 20245 77Th AVENUE SOI
KENT, WA 98032
Handler type: (Check all that apply.) Generator Transporter TSDR
RCRA Site ID Number: AZD 980735500
Name: WORLD RESOURCES CO
Address: 2113 WEST SHERMAN ST.
PHENIX AZ 85043
Handler type: (Check all that apply.) Generator Transporter TSDR
RCRA Site ID Number:
Name:
Address:
Handler type: (Check all that apply.) Generator Transporter TSDR
RCRA Site ID Number:
Name:
Address:
Handler type: (Check all that apply.) Generator Transporter TSDR
RCRA Site ID Number:
Name:
Address:
Handler type: (Check all that apply.) 🗖 Generator 🚨 Transporter 🚨 TSDR

BOOK 1: 1996 FORMS AND INSTRUCTIONS

34

Page _

1996 01

OFF-SITE IDENTIFICATION INFORMATION FORM ANSWER SHEET

Please enter your RCRA Site ID number and site name at right, before making as many copies of this two-sided answer sheet as you will need.

PLEASE ENTER:
Your RCRA Site ID #: WAD 980738546
Site name: ALASKAN COPPER WORKS
· · · · · · · · · · · · · · · · · · ·
FOR ECOLOGY USE ONLY:
Date received:
1

Please complete this form if your facility received dangerous waste from off-site or shipped dangerous waste off-site during 1996.

Please type or print legibly in blue or black ink
RCRA Site ID Number: _ILD 984 908 202 Name: _SAFETY KLEEN
Address: 6303 212 AVE
RCRA Site ID Number:UTD 981552425 Name:SLT_EXPRESS
Address: 1900 SO. IN DUSTRIAL RD SALT LAKE CITY LIT 8 Handler type: (Check all that apply.) Generator Transporter TSDR
RCRA Site ID Number: ORD 981766124 Name: SAFETY KLEEN
Address: 16540 130TF AVE SE Bldg B Clackawas, OR 97015 Handler type: (Check all that apply.) Generator Transporter TSDR
Comments:
Pane

BOOK 1: 1996 FORMS AND INSTRUCTIONS

END OF REPORT (Attach this page as the last page of your submission)

Page _____

BOOK 1: 1996 FORMS AND INSTRUCTIONS

510 -944-9098

IM Brown



** Transmit Conf.Report **

Jun 23 '97 15:22

ALASKAN COPFER WORKS> 915109449098		
115.	0101	
Hode	NORMAL.	
Time	11*13*	
Pages	18 Fage(s)	
Kesult	0 K	